

## JOB ACRONYMS

AMS	AMS Last Gasp
ATRF	Auto Transformer
CTR	Cut
DIMMING	Dimming Lights
ELBOW	Elbow
Emergency	Fire Call or Emergency
FDR	Feeder
FLICKER	Flicker
FUS	Fuse
ISO	Isolation
LightsOn	Customer Lights On
LightsOut	Lights Out
OTRF	OHTransformer
PARTIAL	Partial Lights
PPOD	Primary Point of Delivery
RCL	Recloser
SER	Service
SOX	Substation
SWC	Switch
TOXT	Transmission
UTRF	UG Transformer
WRSDWN	Wires Down
xxx	Transmission

# Acronyms

The table below provides a description of all acronyms indicated in the Assessment and Reconnaissance forms.

Acronym	Description
35'5	Pole Height and Class
PTP	Pole Top Pin
S8FG	Single 8ft fiber glass arm
D8FG	Double 8ft fiber glass arm
HD8FG	Heavy Duty 8ft fiber glass arm
XHD8FG	Extra Heavy Duty 8ft fiber glass arm
S10FG	Single 10ft fiber glass arm
D10FG	Double 10ft fiber glass arm
HD10FG	Heavy Duty 10ft fiber glass arm
XHD10FG	Extra Heavy Duty 10ft fiber glass arm
S12FG	Single 12ft fiber glass arm
LA	Lighting Arrester
CO	Cutout
1SPCR	1 Spool Conversion Rack
1SPR	1 Spool Rack
3SPER	3 Spool Extension Rack
1SPER	1 Spool Extension Rack
12M	12M Screw Anchor
20M	20M Screw Anchor
25M	25M Screw Anchor
39M	39M Screw Anchor
58M	58M Screw Anchor
DG6M	6M Down Guy
DG11M	11M Down Guy
DG18M	18M Down Guy
DG25M	25M Down Guy
OH6M	6M Overhead Guy
OH11M	11M Overhead Guy
OH18M	18M Overhead Guy
OH25M	25M Overhead Guy
PB	Pole Band
FIR	Fiber Glass Insulating Rod
PDE	Primary Dead End